COST SUMMARY - CLUB DOUBLE STOREY VS SINGLE STOREY OPTION

COST SOMMART - CLOB DOOBLE STOKET VS SINGLE STOKET OF HON					
CLUB DOUBLE STOREY OPTION			SINGLE STOREY OPTION - In accordance with Council's Pavilion Development Policy		
Submitted Club Cost Plan - Club Double Storey Option as at August 2018	\$	3,786,935.00			
Aligned project escalation to May 2020	\$	293,065.00			
Submitted Club Cost Plan - Club Double Storey - Total Estimated Project Cost as at May 2020	\$	4,080,000.00			
Council Cost Plan - Peer Review of Club Double Storey as at May 2020	\$	5,901,000.00			
Total Cost increase identified items not included in the club proposal (A+B)	\$	892,000.00			
Council Cost Plan - Club Double Storey Option - Total Estimated Project Cost as at May 2020 st	\$	6,793,000.00	Council Cost Plan - Council Single Storey Option - Total Estimated Project Cost as at May 2020*	\$	5,740,000.00
Less Federal Funding	\$	2,000,000.00	Less Federal Funding - TBC	\$	2,000,000.00
Total Council Contribution Required for the Club Double Storey Option Proposal	\$	4,793,000.00	Total Council Contribution Required for the raised Single Storey Pavilion	\$	3,740,000.00

A. Cost Increase by Statutory Compliance not included in club scheme as follows:

1 No ambulant toilets provided in Umpire's rooms, Public or Participants Amenities.

- 2 Generally no Change Room provision for persons with a disability for participants (players) which is a BCA/NCC requirement.
- 3 Access to ground floor will require ramps and steps due to the lower floor level required to be raised approximately 600mm above flood level.
- 4 Insufficient showers / toilets in Change Rooms to comply with the BCA. Public amenities are insufficient for the sq. m area of the Multi-purpose room.
- 5 Canteen / Kitchen grease trap Yarra Valley Requirement
- 6 Currently there are no DDA carparks and it appears has not been allowed for in the Clubs proposal / cost plan.

B. Cost increase - Standard pavilion components not included in the club scheme as follows:

- 7 Wall hung urinals to be replaced with toilet pans so as to cater for Mixed Gender.
- 8 No provision for Community Tea Making associated with Multi-purpose room, separate to Kitchen.
- 9 Swipe card system as per the Pavilion Development Policy
- 10 Roller shutters to windows as standard pavilion component
- 11 Change Rooms could be more flexible with the potential of opening them into one space if they were colocated. Allowance for roller shutters between change rooms.
- 12 Total Storage Area in general and for community groups is less than required under the Pavilion **Development Policy**
- 13 Club proposal change rooms at 34 40 sq. m are less than the Pavilion Development Policy at 45 sq m.
- 14 Additional spectator canopy overhangs
- 15 Additional kitchen area
- 16 Standalone bin enclosure as per the pavilion / waste management guidelines
- 17 ESD items double glazing and solar panels as per Pavilion Development Policy. It is not clear whether the Club Cost Plan has an allowance for solar panels.

* Includes standard project cost inclusions as follows:

18 Preliminaries **

19 Design / Construction Contigency **

20 Professional Fees / Project Management Fees**

21 Authority / Council Fees**

- 22 Temporary Accomodation Facilities / Decant
- 23 Furniture, Fittings and Equipment (FF&E) and AV Equipment

**Note: some of the above listed items have been included in the Club Cost Plan but increase according to project cost.

Page 1